


Index No. U-13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S 1/10 Corner common to sections 27 & 28



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1918  
 Original monument 1" x 36" I.P. w/ Br. Cap - W.C.  
W.C. set 1.80 chains north of true

Species	Bearing	Trees	Distance
<u>Cedar</u>	<u>Co. 24</u>	<u>Also W.C. set 2.00 chains east</u>	
<u>9</u>	<u>4</u>	<u>Tan Cedar</u>	<u>5 3</u>
<u>N59E</u>	<u>N24W</u>	<u>S88E</u>	<u>N54 1/2 E</u>
<u>11 lks</u>	<u>37 lks</u>	<u>19 lks</u>	<u>30 lks</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_