


Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 14R R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
 Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

	Bearing	Trees
Species <u>Poplar</u>	<u>Poplar</u>	<u>Tam.</u>
Diameter <u>7</u>	<u>6</u>	<u>8</u>
Bearing <u>N40W</u>	<u>N73E</u>	<u>S42E</u>
Distance <u>85 lks</u>	<u>120 lks</u>	<u>152 lks</u>

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1917 By GLO  
 Location filed \_\_\_\_\_  
 Monument Fed. 4" sq. marked cedar post - set  
2" x 36" i.p. w/ Br. cap - no evidence of  
original BTS - accepted as local error.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

	W. Oak	Cedar	W. Oak
Species <u>Poplar</u>	<u>W. Oak</u>	<u>Cedar</u>	<u>W. Oak</u>
Diameter <u>8</u>	<u>12</u>	<u>12</u>	<u>14</u>
Bearing <u>N77 1/2 E</u>	<u>S81 E</u>	<u>S49 1/4 W</u>	<u>N27 W</u>
Distance <u>167 lks</u>	<u>305 lks</u>	<u>267 lks</u>	<u>145 lks</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_