Index No. Y-14

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____

SW 1/16 Corner common to sections 34




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918

Original monument 1"x36" I.P. w/Br. Cap

### Original Evidence Found

Year of search _____ By _____

Monument found _____

| Bearing Trees | | | | | | | |
|---|---|---|---|---|---|---|---|
| Species | Cedar | Cedar | | | | | |
| Diameter | 14 | 10 | | | | | |
| Bearing | S 8 W | S 47 1/4 E | | | | | |
| Distance | 40 lks | 58 lks | | | | | |

| Original Bearing Trees Found | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

| Bearing Trees, Reference Objects | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

| Bearing Trees, Reference Objects | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____