Index No. A 3

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____

N 1/4 6 Corner common to sections 6 AND 31-143-31




○ = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed _____

Original monument _____

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed Sec. of State

Monument Set 1x36" Alw/brass cap proportionally

1/4 S31

no. orig. evidence S6

1919

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | W. oak | W. oak | | |
| Diameter | 5" | 8" | | |
| Bearing | S75 1/2E | N32W | | |
| Distance | 139 Lks | 113 Lks | | |

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____