


Index No. A 7

CASS COUNTY LAND CORNER RECORD



T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____

N1/4 5 Corner common to sections 5 AND 32-143-31

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURO
Location filed COUNTY RESERVE PLAT "E-57"
Monument 2 1/4" x 4 1/8" I.O.M.
1915, Curly Bark 2" 1507 FVA STAKE & OLD B.T. SET IN
also on microfilm - roll 105 BK 60 P. 63

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLC
Set 1 X 3/16" 1/4" w/ brass cap proportionally
1/4 532
55
1919

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>W. Pine</u>	<u>Wire Fence</u>
<u>12"</u>	<u>12"</u>	<u>N/E</u>
<u>N 66 E</u>	<u>S 35 1/4 E</u>	<u>from corner</u>
<u>92 LKS</u>	<u>71 LKS</u>	

Subsequent Corner Restoration

Year surveyed 1925 By Miss Hwy Dept.
Location filed R/W map in Recorder's of Fire - Walker to
Monument Cass Lake
1" iron pipe w/ brass cap 1405.9' E. of q
tangent

1915 - Sco H's Baldwin - microfilm - roll 115 BK 81 P. 11
set corner proportionally
P. 35 set non 3' W. of fence corner
dig pit 3' west

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LITTLE PONDROSA
R.F. SCHNEIDER 1967

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____