


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 5 Corner common to sections 4, 5 AND 32, 33-143-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURD

Location filed COUNTY RESURVEY PLAT "E-57"

Monument 2" x 48" I.M.

1915, CURD, BOOK "C" P. 506 TWO STAKE AND STUMPS OF  
OLD GOVT B.T.S. P. 509 SET I.M.  
also on microfilm - y011115 BK 81 P. 6, 34  
iron on top of oak piling

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>OAK</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>20"</u>
Bearing	<u>N15-30E</u>	<u>N22-30W</u>	<u>S49W</u>
Distance	<u>224.0'</u>	<u>170.0'</u>	<u>207.4'</u>

1915 ties

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO

Find 2 1/2" IIP and 12" elm stump S49 1/2 W 122 LKS,  
dead elm N24 1/2 E 187 LKS. Set 2x36" IIP. w/ brass  
cap N14 alongside 2 1/2" iron T143N R31W  
S32/S33  
S5/S4  
T142N

Bearing Trees, Reference Objects 1919

	<u>W. Oak</u>	<u>W. Oak</u>	<u>R. Oak</u>
	<u>16"</u>	<u>10"</u>	<u>7"</u>
	<u>N31 1/2 E</u>	<u>S53 W</u>	<u>N 68-45 W</u>
	<u>360 LKS</u>	<u>289 LKS</u>	<u>277 LKS</u>

Subsequent Corner Restoration

Year surveyed 1999 By Landecker & Assoc

Location filed CCSO

Monument Certificate of Survey indicates  
Brass Cap monument in place.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_