


Index No. E 19

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 11 Corner common to sections 2, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Y. Pine Y. Pine \_\_\_\_\_  
Diameter 20" 24" \_\_\_\_\_  
Bearing N20E S52W \_\_\_\_\_  
Distance 87 lks 58 lks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1910 By JOHN CURE  
Location filed COUNTY SURVEY RECORD BOOK 'A' P 300-301  
Monument SET 3X3X48" OAK POST FROM ORIG. BITS; 20" Y.  
PINE N10W 57.12; R7" Y. PINE S63-35W 38.28'  
also on microfilm. Roll 105 BK 50 P 14-15

Evidence of Subsequent Corner Restoration p. 22

Year of search 1918 By GLC  
Set 1" x 36" Br. Cap from remains of  
original BTs

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Aspen R. Oak  
6 6  
N75-45W S70-15W  
29 lks 55 lks

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_