


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 12 Corner common to sections 112



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>Tam</u>	<u>Tam</u>
Diameter <u>4"</u>	<u>3"</u>
Bearing <u>N 4 E</u>	<u>South</u>
Distance <u>4 lks</u>	<u>2 lks</u>

Original Bearing Trees Found		
Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration p. 20

Year surveyed 1917 By GLO  
Location filed \_\_\_\_\_  
Monument 1" x 36" Br. Cap set from original bearing trees

Evidence of Subsequent Corner Restoration

Year of search 1981 By G.H. Stevenson  
fd. Br. Cap

Bearing Trees, Reference Objects		
Species <u>Spruce</u>	<u>Spruce</u>	_____
Diameter <u>4</u>	<u>4</u>	_____
Bearing <u>N 51/2 W</u>	<u>S 43/2 E</u>	_____
Distance <u>8 lks</u>	<u>11 lks</u>	_____

Bearing Trees, Reference Objects		
Species <u>Spruce</u>	<u>Spruce</u>	<u>Spruce</u>
Diameter <u>8</u>	<u>6</u>	<u>7</u>
Bearing <u>S 43 E</u>	<u>N 51 W</u>	<u>S 32 W</u>
Distance <u>7.42'</u>	<u>4.94'</u>	<u>15.77'</u>
<u>GLO</u>	<u>GLO</u>	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_