


Index No. E-24

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/16 Corner common to sections 1 & 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1" X 3/16" Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Ash Aspen \_\_\_\_\_  
Diameter 5 4 \_\_\_\_\_  
Bearing N78 1/2 E S82 1/2 E \_\_\_\_\_  
Distance 4 lks 52 lks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1969 By Co. Hwt Dept.  
Location filed Co Rd #72  
Monument US GLO Corner in place

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Elm Elm W. OAK  
11" 10" 6"  
S16E N40W N4W  
43.90' 33.30' 42.40'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970  
Mar 2003 P. Schoberg #14700  
Cert. of Surv. shows Mon. Found

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_