Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 12 Corner common to sections 1, 12 AND 6, 7-142-30

ALSO mc # 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	Y. Pine	R. Oak
Diameter	25"	10"
Bearing	S 5 E	N 61½ W
Distance	10 lks	10 5 lks.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed _____

Monument Set 1"x36" I.P. w/ Br. Cap for W.C. 0.85 chains south of true position as determined from original BT: 15" R. Oak stump with marks visible.

Bearing Trees, Reference Objects

Species	Oak	Pine		
Diameter	8	12		
Bearing	S 15½ E	S 30¾ W		
Distance	82 lks	13 lks		

Evidence of Subsequent Corner Restoration

Year of search 1969 By CO Hwy Dept

CO RD # 77

2" I.P. in place

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - TRADING POST BAY

R.F. SCHNEIDER R69

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____