


Index No. F-21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
N 1/16 Corner common to sections 11 & 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
 Original monument Br. Cap - 1" x 3/16"

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>R. Oak</u>	<u>R. Oak</u>	_____	_____
Diameter	<u>5</u>	<u>6</u>	_____	_____
Bearing	<u>N 70 E</u>	<u>S 70 W</u>	_____	_____
Distance	<u>18 lbs</u>	<u>35 lbs</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1979 By Gary Stevenson
 Location filed _____
 Monument Found GLO monument bent. Set
2" x 24" concrete filled galvanized iron
pipe with marked brass cap down 6".

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>W. Pine</u>	<u>W. Oak</u>
Diameter	<u>13"</u>	<u>13"</u>	<u>8"</u>
Bearing	<u>N 40 W</u>	<u>S 65 W</u>	<u>S 63 E</u>
Distance	<u>40.43'</u>	<u>35.71'</u>	<u>34.16'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1982
Doc # 261361