


Index No. 61

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W 1/4 7 Corner common to sections 7



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees
Species	<u>W. Birch</u>	<u>W. Birch</u>
Diameter	<u>7"</u>	<u>7"</u>
Bearing	<u>S 52W</u>	<u>S 85E</u>
Distance	<u>11 lks</u>	<u>20 lks</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD  
Location filed COUNTY RESURVEY PLAT "E-57"  
Monument IRON MONUMENT  
1915 - E.B. HOBST COUNTY BOOK "C" P.44 - SET I.M.  
also on micro film - roll 115 BK 78 P.90  
also set N: S 1/16's - SET I.M's

Evidence of Subsequent Corner Restoration

Year of search 1991 By David Landecker  
Found 2" iron pipe up 14". Set aluminum cap on found 2" iron pipe

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>N. Pine</u>	<u>W. Pine</u>
<u>9"</u>	<u>10"</u>	<u>8"</u>
<u>N46W</u>	<u>N57E</u>	<u>S16W</u>
<u>24.14'</u>	<u>6.75'</u>	<u>22.09'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
Doc # 327266

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_