


Index No. G-23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
C 44 Corner common to sections 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1" x 3/16" Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. Oak Aspen _____
Diameter 8 6 _____
Bearing N56E S43W _____
Distance 39 6 blks _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1969 By Co. Hwy Dept.
Location filed Co Rd #72
Monument 1 1/2" I.P. in place

Evidence of Subsequent Corner Restoration

Year of search 1984 By T. Freeman and USFS
personnel C. Krause, G. Brauma, J. Allison

End 1917 brass cap monument 14" below surface
1 1/2" I.P. is N45°W 9.15' from brass cap

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____