


Index No. G 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 8 Corner common to sections B, 9



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1873  
Original monument POST

**Bearing Trees**

Species	<u>1 Pine</u>	<u>1 Pine</u>	_____
Diameter	<u>8</u>	<u>8</u>	_____
Bearing	<u>N 79 W</u>	<u>N 7 E</u>	_____
Distance	<u>14 lks</u>	<u>17 lks</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1917 By EB. Hoest  
Location filed COUNTY BOOK B" P 521-526  
Monument SET 2x48" BRILLER FLUE  
1927, JOHN GREENE, COUNTY RESURVEY PLAT "E 58"  
I.M.

**Evidence of Subsequent Corner Restoration**

Year of search 1917 By Hoest  
microfilm - roll 115 BK 78 P. 122  
set on corner run east  
P. 132 - set 2x48" I.M. 36" in ground  
also set 2x48" at 5/16

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 5-4-04 By Latulip # 25299  
Location filed CCRO # A000487352  
Monument No monument found (Reference corner only - new road to be put in)  
Reference Ties:

<u>5/8" REBAR</u>	<u>5/8" REBAR</u>	<u>5/8" REBAR</u>
<u>N 16° W</u>	<u>N 90° E</u>	<u>S 3° E</u>
<u>14.01'</u>	<u>23.72'</u>	<u>63.79'</u>

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - KAPEKONA SPRINGS  
JOHN CURD 1913

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_