


T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
MC# 46 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Balsam Poplar</u>	_____	_____
Diameter	<u>6</u>	<u>10</u>	_____
Bearing	<u>S 33W</u>	<u>N 21W</u>	_____
Distance	<u>8 lks</u>	<u>26 lks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E. B. HOEST
 Location filed COUNTY BOOK "B" P. 521-526
 Monument FND W.C. M.C. I.M.
1916, JOHN CURG - COUNTY RESURVEY PLAT "E-59" I.M.
1916, E. B. HOEST, BOOK "C" P. 503 SET W.C. M.C. FROM
BALLMAN INFO. SET I.M. - also on microfilm roll 105

Evidence of Subsequent Corner Restoration

Year of search 1925 By Miss HWY Dept.
RLW map in Recorder's office - Walker to Cass Lake
1917 - also on microfilm - roll 115 BK 78 P. 110
P. 126

Bearing Trees, Reference Objects

Species	<u>DOUBLE OAK</u>	<u>ASH</u>	<u>B. OAK</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>18"</u>
Bearing	<u>N 32W</u>	<u>S 68W</u>	<u>NW</u>
Distance	<u>28.5'</u>	<u>14.5'</u>	<u>60.0'</u>

1916 TIES

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____