


Index No. L5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
E 14 18 Corner common to sections 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Y. Pine</u>	<u>Birch</u>	_____	_____
Diameter	<u>5</u>	<u>4</u>	_____	_____
Bearing	<u>S 16 W</u>	<u>N 82 E</u>	_____	_____
Distance	<u>15 lks</u>	<u>7 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. Horst
Location filed COUNTY RESURVEY PLAT "E-59"
Monument 2x48" I.M.
1921, E. B. Horst, Book "C" P473 SET I.M.

Evidence of Subsequent Corner Restoration

Year of search 1914 By Cuyo
microfilm - roll 115 BK 92 P. 10.
Set corner.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - David Landsaker
Doc # 326710
Found 1 1/2" iron pipe up 80". Set 2' x 48"
iron pipe with brass cap and magnet at
base up 9". Ties: 23' Norway Pine
N 85 W 45.09'; 9" Red Oak S 20 E 29.88';
7 1/2" Birch East 21.16'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____