


Index No. 0-9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 116 Corner common to sections 20 & 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1" x 36" l.P. w/ Br. Cap

Bearing Trees	
Species <u>Oak</u>	<u>Birch</u>
Diameter <u>6</u>	<u>6</u>
Bearing <u>S 76° E</u>	<u>N 40 1/2° W</u>
Distance <u>22 lks</u>	<u>27 lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1964 By Pete Meyer

Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.  
6" Oak S 76° E 14.52' now 12" at 19.1'  
6" Birch N 40 1/2° E 17.82' now 11" stump

Bearing Trees, Reference Objects

Species <u>Oak</u>	_____
Diameter <u>9"</u>	_____
Bearing <u>N 19 1/2° W</u>	_____
Distance <u>45.45'</u>	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1964

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_