


Index No. R-13-14

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 574 Coordinates: X _____ Y _____
MC # 36 Corner common to sections 22, 27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	<u>Y. Pine</u>	<u>Y. Pine</u>	_____	_____
Diameter	<u>16</u>	<u>16</u>	_____	_____
Bearing	<u>N25W</u>	<u>S61W</u>	_____	_____
Distance	<u>19 lks</u>	<u>19 lks</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By GLO

Location filed _____

Monument 1" x 3/16" Br. Cap from which original
B.T.s: 24" Pine Stamp S61W 19 lks
24" Pine Stamp N25E 19 lks (error in
original bearing)

Evidence of Subsequent Corner Restoration

Year of search 1922 By Auditors Plat of Govt
Lot 5 - Sec 22-142-31 in Recorders office
shows V.S. J.M. M.C.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Sugar Lot 5</u>
Diameter	<u>8</u>	<u>2 1/2" gal. I.P.</u>
Bearing	<u>S38 3/4 W</u>	<u>N41-11E</u>
Distance	<u>133 lks</u>	<u>5.52 chs</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

R-13.14

Subsequent Corner Restoration

Year surveyed 1915 By P.M. SCOTT

Location filed microfilm - roll 115 BK 78 P. 66

Monument Find SW orig. B.T. set Birch hub
Pine stump 10" N6-15E 25.10'
Pine stump 14" N60-33W 26.10'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PILLBURY ADDITION TO WALKER
L.R. Lothrop 1896

PLAT - AUDITORS PLAT OF GOVT LOT 5 SEC 22
E.B. Hoest 1922

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____