


142 R. 31 M. 5TH Coordinates: X _____ Y _____
MC # 34 Corner common to sections 27, 34



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Species	Bearing	Trees
<u>W. Pine</u>	<u>W. Pine</u>	
<u>15</u>	<u>18</u>	
<u>S 80 E</u>	<u>S 55 W</u>	
<u>30 lks</u>	<u>10 lks</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1915 By JOHN CURRO
 Location filed COUNTY RESURVEY PLAT "E-61"
 Monument 2 1/4 x 4 1/8" I.M. W.C.M.C. 7' SOUTH
1915, E.D. HERSI, Book 2 P. 511 From Both B.T. Stumps
P. 515 set 2 1/4 x 4 1/8" I.M.
also on microfilm - roll 105 BK 60 P. 11, 55, P. 80 -
set I.M. W.C. 7' S. of tree - one 6 1/2 x 30 x 12"
 Bearing Trees, Reference Objects 6' 5"

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration
 Year of search 1921 By GLO
Set 1" x 3/8" Br. Cap for WC - 15 lks south of
true position from stumps of original B.Ts. Fed
2 1/2" gal. I.P. 5 lks north set by Co. Sur. From Br. Cap
original B.Ts: 20" W. Pine stump N44W 9 lks
24" W. Pine stump N78 1/4 E 22 1/2 lks

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Pine</u>	<u>Birch</u>	
<u>8</u>	<u>10</u>	
<u>S 80 E</u>	<u>S 58 1/2 W</u>	
<u>14 lks</u>	<u>74 lks</u>	

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - LONG-MAY
WALTER E. CURRO 1979