


Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

N 1/4 - 5 Corner common to sections 5 AND 32 - 144-25



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1872  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species SPRUCE FIR \_\_\_\_\_  
 Diameter 4" 4" \_\_\_\_\_  
 Bearing N 30 E S 8 W \_\_\_\_\_  
 Distance 30 LKS 30 LKS \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed SEPT 1984 By K. WHITEHORN  
 Location filed CERT OF SURVEY DOC. # 277427  
 Monument SET 2" x 5' BRASS CAPPED, CONCRETE  
FILLED IRON PIPE AT LOST POSITION

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species BURR OAK W. BIRCH ELM SIGN POSTS  
 Diameter 7.4" 7.2" 6.5"  
 Bearing N 23° E S 89° E S 47° W N & W  
 Distance 18.39 21.64 10.25 BOTH 3.0'  
ALL TO 16 d NAILS IN SIDE

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_