Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 8 Corner common to sections 4, 5, 8, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Bearing Trees

Species	SPRUCE	CEDAR	CEDAR	CEDAR
Diameter	4"	3"	14"	10"
Bearing	S14E	N42E	N30W	S75W
Distance	15 LKS	30 LKS	50 LKS	40 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____