

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Page \_\_\_\_\_ of \_\_\_\_\_

Corner common to sections \_\_\_\_\_


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

143 R. 25 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 10 Corner common to sections 10, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1872  
 Original monument POST

Bearing Trees  
 Species SPRUCE BIRCH  
 Diameter 6" 7"  
 Bearing N84W N75E  
 Distance 12 LKS 15 LKS

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURD  
 Location filed COUNTY SURVEY RECORD BOOK B" P. 4-11  
 Monument FLYNN FND OLD CORN B.T.S IN 1908 SET STAKE KIRK SET I.P. 5' LOW. CURD FND FLYNN'S B.T.S. 30" W. PINE STUMP SB 4E 26.40', 4" ASPEN N77-40 W 48.47'

Bearing Trees, Reference Objects  
 Species POPLAR C.F.P. BALM OF GLEAD  
 Diameter 4" CEDAR 6"  
 Bearing N 69-22W S 87-31W N 27-11 W  
 Distance 48.47' 36.85' 75.30'

Evidence of Subsequent Corner Restoration

Year of search 1908 By JAMES FLYNN  
COUNTY BOOK C" P 184 FND OLD CORN B.T.S. DOWN SPRUCE 6" N 84W 12 LKS. SET POST 1914, F.A. DANNER, BOOK C" P 549 FND CURD'S CORNER. - also on microfilm - roll 115 BK 94 P. 27-28

Bearing Trees, Reference Objects  
W. PINE STUMP ASPEN  
30" 4"  
S 84E N 76W  
26.5' 47.5'  
1908 TIES

G-17

Subsequent Corner Restoration

Year surveyed 1965? By Co. Hwy Dept.  
 Location filed Co. RD # 65  
 Monument Found 1 1/2" I.P. in place

1971 - Co. Hwy Dept - Co. RD # 74  
1" I.M. in place  
TIES: P.P. NW 156.9', P.P. SW 198.6'  
1x2" Hub W. 63.0'

Hwy Dept found USFS Brass cap 0.25'  
W. of 4 N-S RD same ties as of 1971 -  
EXCEPT hub W. moved to 80' W.

4/5/84 - Co. Surveyor, U.S.F.S.  
Concrete monument set in 1965 gone  
End P.K. set from 1971 Co. Hwy Dept ties  
PP NW 156.9, P.P. SW 198.6'  
set U.S.F.S magnet under P.K. nail  
2' down - also nail in northerly side  
wood fence post east 67.88'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1965  
Set 6" x 24" cylindrical concrete monument  
with 3" stamped bronze tablet.  
Cedar Post 4" x 4" x 60" N 38E 23.7'