


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J 15

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species SPRUCE W. PINE
 Diameter 6" 5"
 Bearing 553E N65E
 Distance 5 LKS 6 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1976 By BLM
 Location filed SEC. OF STATE
 Monument SET 26" COPPER-COATED STEEL STAKE 6" BELOW ROAD SURFACE
7143N R25W
1/4 5/0
5/5

Evidence of Subsequent Corner Restoration
 Year of search 7 By Geo Ralph
Microfilm - roll 115 BK 82 P. 48
Find old post and old B.T. 8" Spruce
N44-30E 6.5'

Bearing Trees, Reference Objects BLM 1976
 Species ALUMINUM/UP ALUM. POST/UP
 Diameter 2 1/2 x 20" 2 1/2 x 20"
 Bearing N6E N31W
 Distance 73.0' 85.9'

Bearing Trees, Reference Objects
Cedar Pine stub
5"
N5-30E S19W
46.2' 42.3'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____