


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. R5 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1872
Original monument POST

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	<u>SPRUCE</u>
Diameter <u>14"</u>	<u>6"</u>	<u>4"</u>
Bearing <u>S13W</u>	<u>S20E</u>	<u>N26W</u>
Distance <u>60 LKS</u>	<u>100 LKS</u>	<u>30 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1908 By JAMES FLYNN
Location filed COUNTY BOOK "C" P 184
Monument ~~POST~~ FIND OLD GOVT B.T.S: 12" ASPEN S20E
100 LKS, 6" SPRUCE N26W 30 LKS.

Year of search 1914 By F. A. PINNER
COUNTY BOOK "C" P 548 FIND CORNER AND SE & NW
B.T.S. and 1908 B.T.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ASPEN</u>	<u>22"</u>	<u>N5W</u>	<u>58.7'</u>

also on microfilm - roll 115 BK 94 P. 17, 29
set witness post 4x4x48", 24' North

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ASPEN</u>	<u>12"</u>	<u>N28-23W</u>	<u>77.5'</u>
			<u>1914 B.T.</u>

J-21

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 1965 By Co Hwy Dept
Location filed _____
Monument assumed corner in E-W Rd
and G Rd N: S 1/2' subcut
16" oaks w. 86.0', P.P. NW 41.0'
stay 719+13.0
1984 4/5 - Co Surveyor, USFS
Find P.K. nail

Year of search 1994 By Terry Freeman
Found P.K. nail + stump of 1965 Oak bearing tree. Removed
11-23-94 placed a 2"x30" flanged mon. w/ brass
cap in centerline of County Road #105, dwn 0.2'
8' steel sign post N40E, 73.45'; lower pole, N24W,
45.54'; 8" Burr Oak, S7W, 135.60'; 8' steel sign
post 539 E 87.73'
3-16-95 Cert. Filed by Terry Freeman, Rls 21367,
Doc. No. 365392

1965 - Ekstrom, USFS believed
road has destroyed B.T.

Jan. 2005 T. Freeman #21367
Cert. of Survey shows monument found

July 2005 T. Freeman #21367
Cert. of Survey shows monument found