


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____

N 1/4 24 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>S80W</u>	<u>N36E</u>	_____
Distance	<u>50 LKS</u>	<u>40 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument END USFS 2 1/2" I.P. W/ BRASS CAP T143N R25W

Evidence of Subsequent Corner Restoration

Year of search 1966 By MILD STEFAN
Set 2" x 60" galvanized steel pipe with bronze cap.
1994 10-25 By Terry Freeman Found 2" x 60" iron pipe. Left as found. 3-16-95 Cert. Filed by Terry Freeman, RLS #21367. Doc #365398

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	_____
Diameter	<u>3"</u>	<u>3"</u>	_____
Bearing	<u>N74W</u>	<u>N39W</u>	_____
Distance	<u>52 LKS</u>	<u>26 LKS</u>	_____

USFS TIES

Bearing Trees, Reference Objects

<u>Spruce</u>	<u>Spruce</u>	<u>Black Spruce</u>
<u>3"</u>	<u>3"</u>	<u>5"</u>
<u>N39W</u>	<u>N74W</u>	<u>S82W</u>
<u>17.30'</u>	<u>34.60'</u>	<u>130.75'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILD STEFAN - 1966 FILED IN 1979
Doc #246210

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____