


Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1867
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	
Diameter <u>10"</u>	<u>12"</u>	
Bearing <u>N20W</u>	<u>S30W</u>	
Distance <u>39LKS</u>	<u>11LKS</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument Find 2" ITASCA Co. Alum. Pipe w/ALUM. CAP

Evidence of Subsequent Corner Restoration

Year of search 1994 10-14 By Terry Freeman
Found 1" iron pipe w/stamped alum. cap. lat as found
216-95 Cert. Filed by Terry Freeman, RLS-213657,
Doc #365399.

Species	Bearing	Trees	Reference Objects
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>7143N</u>
Diameter <u>4"</u>	<u>12"</u>	<u>10"</u>	<u>5131</u>
Bearing <u>S1E</u>	<u>S64W</u>	<u>N51W</u>	<u>5241</u>
Distance <u>48LKS</u>	<u>5LKS</u>	<u>41LKS</u>	<u>R25W</u>
			<u>1975</u>

Species	Bearing	Trees	Reference Objects
<u>Aspen</u>	<u>Aspen</u>	<u>Aspen</u>	
Diameter <u>5"</u>	<u>5"</u>	<u>9"</u>	
Bearing <u>N151W</u>	<u>S87W</u>	<u>S51W</u>	
Distance <u>17.07</u>	<u>136.60</u>	<u>32.30</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____