


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X Y  
E 1/4 24 Corner common to sections 24 W.C. 1, 25 CH. South



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument POST W.C.

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species TAM.  
Diameter 7"  
Bearing S 57 W  
Distance 9 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1976 By BLM  
Location filed SEC. OF STATE  
Monument END 2" ITASCA Co. Alum Mon w/ Alum. Cap

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species BIRCH ELM ELM 24  
Diameter 9" 7" 10" RKSW  
Bearing N 25 E S 15 E S 39 W 1975  
Distance 17 1/2 LKS 2 LKS 11 1/2 LKS  
ITASCA Co. TIES.

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_