


Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 2422, 2728



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees			
Species	<u>BIRCH</u>	<u>BIRCH</u>	<u>BIRCH</u>	<u>BIRCH</u>	
Diameter	<u>10"</u>	<u>10"</u>	<u>16"</u>	<u>6"</u>	
Bearing	<u>S58W</u>	<u>N11W</u>	<u>N78E</u>	<u>S17E</u>	
Distance	<u>11LKS</u>	<u>18LKS</u>	<u>20LKS</u>	<u>16LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEL. OF STATE
Monument ENO 1" ALUM PIPE SET 2 1/2 X 26" ALUM CAP
W/ALUM CAP T143N R25W
521/522
528/527

Evidence of Subsequent Corner Restoration

Year of search 1989 By Walter Curo
Found 2 1/2" x 28" aluminum monument

		Bearing Trees, Reference Objects			
Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	
Diameter	<u>6"</u>	<u>5"</u>	<u>7"</u>	<u>6"</u>	
Bearing	<u>N68E</u>	<u>S45E</u>	<u>S66W</u>	<u>N12W</u>	
Distance	<u>33 1/2 LKS</u>	<u>42 LKS</u>	<u>37 LKS</u>	<u>81 LKS</u>	

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Maple</u>	<u>Burr Oak</u>
<u>4"</u>	<u>3"</u>	<u>4"</u>	<u>3"</u>
<u>N22W</u>	<u>N23E</u>	<u>S12E</u>	<u>S12W</u>
<u>8.79'</u>	<u>26.47'</u>	<u>38.93'</u>	<u>33.70'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - Walter Curo
Doc # 326338

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____