


Index No. T 5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>FIR</u>	_____
Diameter	<u>5"</u>	<u>7"</u>	_____
Bearing	<u>S55E</u>	<u>N65W</u>	_____
Distance	<u>30LKS</u>	<u>18LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1914 By F.A. DONNER
Location filed COUNTY BOOK C P. 551
Monument END NE 8.T STUMP SET 4X4X48" HUB
also on microfilm - roll 115 BK94 P. 48-49

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM
SET 2 1/2 X 3 1/2" ALUM POST w/ ALUM CAP T143N R25W
1/4
530/529
1976

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>DEAD CEDAR</u>	_____
Diameter	<u>4"</u>	<u>5"</u>	_____
Bearing	<u>S10-10E</u>	<u>N60-45E</u>	_____
Distance	<u>29.4'</u>	<u>36.3'</u>	_____

Bearing Trees, Reference Objects

Species	<u>ASPEN</u>	<u>ASPEN</u>	_____
Diameter	<u>8"</u>	<u>12"</u>	_____
Bearing	<u>N80E</u>	<u>N50W</u>	_____
Distance	<u>24LKS</u>	<u>33LKS</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____