Index No. U-11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5th Coordinates: X _____ Y _____

CS 1116 Corner common to sections 28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 3/2001 By CCSO

Found Brass cap IP, RLS 11395, up 1.2', 32'± W. of ℄ CR #137. Survey mon., Sign posts East, 2.6' and South, 3.0'

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Birch	Maple			
10"	6"			
N89°W	S23°W			
48.16'	60.20'			

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____