


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 6 Corner common to sections 5, 6 AND 31, 32 - 144-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	CEDRAR	SPRUCE	SPRUCE	SPRUCE
Diameter	<u>14"</u>	<u>6"</u>	<u>7"</u>	<u>14"</u>
Bearing	<u>S63W</u>	<u>N25W</u>	<u>N43E</u>	<u>S6E</u>
Distance	<u>12 LKS</u>	<u>10 LKS</u>	<u>8 LKS</u>	<u>11 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1922 By GLO
Location filed Sec. of State
Monument End remains of all 4 Govt B.T.S and
set 2x36" i.p. w/brass cap T144N R26W
531/532
56/55

Evidence of Subsequent Corner Restoration

Year of search 1970 By Milo Stefan
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects			
	<u>1922</u>	<u>1922</u>	<u>1922</u>	<u>1922</u>
Diameter	<u>6"</u>	<u>5"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>N35E</u>	<u>S11-15E</u>	<u>S49W</u>	<u>N88-15W</u>
Distance	<u>8.5 LKS</u>	<u>90 LKS</u>	<u>48 LKS</u>	<u>43 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. Pine</u>	<u>20"</u>	<u>557W</u>	<u>66.10'</u>
<u>Ash</u>	<u>9"</u>	<u>S40E</u>	<u>46.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1970 FILED IN 1979
Doc # 246213

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____