


Index No. A 6-7

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 5 and 32-144-26
Left Bank Leech Lake River



EXISTING SURVEYS

Original Government Survey			
Year surveyed	<u>1922</u>		
Original monument	<u>4x4" x 6 1/2" Long Cedar post 4' in ground</u>		

Original Evidence Found	
Year of search	By _____
Monument found _____	

Bearing Trees			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration	
Year surveyed	By _____
Location filed _____	
Monument _____	

Evidence of Subsequent Corner Restoration	
Year of search	By _____

Bearing Trees, Reference Objects			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects			

Subsequent Corner Restoration	
Year surveyed	By _____
Location filed _____	
Monument _____	

Evidence of Subsequent Corner Restoration Found	
Year of search	By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____