Index No. A-B13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 3, 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1922

Original monument Set cedar post 4x4"x6½' 4' in Ground

Bearing Trees

Species _____ _____ _____ _____

Diameter _____ _____ _____ _____

Bearing _____ _____ _____ _____

Distance _____ _____ _____ _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____ _____ _____ _____

Diameter _____ _____ _____ _____

Bearing _____ _____ _____ _____

Distance _____ _____ _____ _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species _____ _____ _____ _____

Diameter _____ _____ _____ _____

Bearing _____ _____ _____ _____

Distance _____ _____ _____ _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____