


Index No. E19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N14 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____
Diameter	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>S39W</u>	<u>N70E</u>	_____
Distance	<u>15 LKS</u>	<u>10 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument SET 2" X 48" BR/CRP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

8' STEEL SIGN POSTS SOUTH 3.0', WEST 2.0'

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>NORTH</u>	<u>S12W</u>	<u>S70W</u>
Distance	<u>1.75</u>	<u>16.31</u>	<u>15.69</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration E19

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY WM. OSUFSEN 1990
Doc. # 323149

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____