


Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5th Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 12 AND 6, 7 - 143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Species	Bearing	Trees	
<u>N. PINE</u>	<u>SPRUCE</u>	<u>ASPEN</u>	<u>SPRUCE</u>
Diameter <u>16"</u>	<u>8"</u>	<u>14"</u>	<u>6"</u>
Bearing <u>S47E</u>	<u>N6E</u>	<u>N75W</u>	<u>S21W</u>
Distance <u>20 LKS</u>	<u>7 LKS</u>	<u>27 LKS</u>	<u>32 LKS</u>

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By BLM

Location filed SEC. OF STATE

Monument SET 24" COPPERWELD 6" BELOW SURFACE
w/ CORNER CAP

7143N
R26W R25W
S1 | S6
S12 | S9

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM OSUFSEN

2" x 24" BR/ CAP

Species	Bearing	Trees, Reference Objects	
<u>ALUM. POST w/ CAP</u>	<u>ALUM. POST w/ CAP</u>	<u>BLM</u>	<u>1976</u>
Diameter <u>2 1/2 x 28"</u>	<u>2 1/2 x 28"</u>		
Bearing <u>N46E</u>	<u>N25W</u>		
Distance <u>49.0'</u>	<u>81.9'</u>		

Species	Bearing	Trees, Reference Objects	
<u>RED OAK</u>	<u>ASH</u>	<u>ALUM. POST</u>	<u>ALUM. POST</u>
<u>6</u>	<u>7"</u>	<u>2 1/2"</u>	<u>2 1/2"</u>
<u>N89W</u>	<u>S73W</u>	<u>N25W</u>	<u>N46E</u>
<u>84.96</u>	<u>87.04</u>	<u>81.90</u>	<u>49.00</u>

Subsequent Corner Restoration E-25

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT BY WM. OSUFSEN
DOC # 323/52