


T. 143 R. 26 M. 514 Coordinates: X _____ Y _____
E 14 12 Corner common to sections 12 AND 7-143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	<u>SPRUCE</u>	<u>W. PINE</u>	
Diameter	<u>6"</u>	<u>8"</u>	
Bearing	<u>N 36 E</u>	<u>S 65 W</u>	
Distance	<u>12 LKS</u>	<u>9 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST

Location filed COUNTY BOOK C 1172

Monument FWD GALT B.T: 10" W. PINE S 65 W 9 LKS

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM

SET 24" COPPER WELD 6" BRAW SURFACE W/ COPPER CAP

T 143 N

R 26 R 25 W

1/4

S 12 / 57

Bearing Trees, Reference Objects

Species	<u>W. PINE</u>	<u>W. BIRCH</u>	
Diameter	<u>16"</u>	<u>16"</u>	
Bearing	<u>S 67-15 E</u>	<u>N 18 W</u>	
Distance	<u>49.5'</u>	<u>36.5'</u>	

Bearing Trees, Reference Objects

Alum Post w/ CAP	<u>2 1/2 x 28"</u>	Alum Post w/ CAP	<u>2 1/2 x 28"</u>
	<u>N 31 E</u>		<u>N 52 W</u>
	<u>42.2'</u>		<u>31.9'</u>

Subsequent Corner Restoration

Year surveyed 1990 By Wm OSUFSEN

Location filed _____

Monument 24" COPPER WELD

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT Wm. OSUFSEN 1990

DOC. # 319611

MARKED W. PINE

18"

S 65 E

44.68

3/2001 CCSO crew found

Copperweld monument down 0.2',

3' E. of & CR #158, ALSO 1976 &

1990 witnesses, add the following

8" N. Pine S 36° W, 115.49 to dbl. hd nail