


Index No. L13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E14 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SET IN BOG - NO B.T.S.
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By GLD
Location filed Sec. of State
Monument Found corner of fences E. S set 2x36"
l.p. w/ Brass Cap
14
516/515
1922

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR-Engineering
Map notes in file
Found brass cap at old fence corner
1975 - DNR - Found l.p. w/cap

Bearing Trees, Reference Objects

Species ELM Basswood
Diameter 16" 14"
Bearing N79-30E N19-00W
Distance 206 LKS 485 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1970 By Wm. OSUFSEN
Location filed _____
Monument Found 2" x 36" BR/CAP
WHITE OAK ASH
11" 9"
N36E N51E
213.70 161.48

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
CERT. Wm. OSUFSEN 1990
Doc. # 319614

6" STEEL SIGN POSTS 4.0 NORTH, 5.4 EAST
8.6 SOUTH

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____