


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Page \_\_\_\_\_ of \_\_\_\_\_

Corner common to sections \_\_\_\_\_


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 22 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>FIR</u>	<u>SPRUCE</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>N45W</u>	<u>S43W</u>	_____
Distance	<u>5LKS</u>	<u>7LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By E.A. Horst  
Location filed COUNTY BOOK 2 P. 171  
Monument WOOD POST & NEW WITNESS TREES.

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR-Engineering  
Map notes in file

1925- Co Hwy Dept - state RD # 4 - Corner

set RR spike at intersection roads

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>EM</u>	_____
Diameter	<u>18"</u>	<u>14"</u>	_____
Bearing	<u>S49 1/4 W</u>	<u>N47E</u>	_____
Distance	<u>53'</u>	<u>53.5'</u>	_____

1916 trees

Bearing Trees, Reference Objects

<u>P.P.</u>	<u>Store</u>	<u>Store</u>
<u>N.B.C.</u>	<u>SW cor.</u>	<u>SE Cor.</u>
<u>SW</u>	<u>NW</u>	<u>NW</u>
<u>48.95'</u>	<u>83.20'</u>	<u>62.70'</u>

Subsequent Corner Restoration

Year surveyed ? By Geo Ralph  
Location filed MicroFilm - roll 115 BK 82 P 45  
Monument Trees:  
spruce SW? 52'  
Elm NE? 54.7'  
Birch NW? 37'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - John Walker - DNR - 1988  
Doc # 303530  
Set 1 1/4 x 1 1/4 x 20" mon. w/ alum cap  
Metal bldg. SE Cor. N26W 88.96'  
28" CMC punch mark w. end S29W 37.62'  
" " " " E. end S38E 43.93'  
Salem turn hall S43E 79.70'

Oct. 2003 M. Stefan #12261  
GLO Monument Found