Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E1/4 21 Corner common to sections 21/22



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Bearing Trees

Species	CEDAR	TAM.
Diameter	5"	5"
Bearing	S78E	N53W
Distance	15 LKS	5 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument 2" x 5'" BR. CAP

8' STEEL SIGN POST NORTH 3.9, EAST 3.9

Bearing Trees, Reference Objects

Species	SPRUCE	CEDAR	CEDAR	
Diameter	4"	13	7"	
Bearing	N48W	S32W	S63W	
Distance	10.42	21.00	22.81	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY WM. OSUFSEN 1990
Doc. # 323160

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____