


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____


Monument: _____

Monument: _____

Index No. P 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 20 Corner common to sections 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument lost

Species	Bearing	Trees
<u>FW</u>	<u>West</u>	<u>Birch</u>
<u>6"</u>	<u>10E</u>	
<u>6LKS</u>	<u>20LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By E. B. HERST

Location filed COUNTY BOOK "C" P. 163

Monument NEW BEARING S

Evidence of Subsequent Corner Restoration

Year of search 1986 By Ken Whitehorn

Set 2 1/2" x 3/4" galvanized iron pipe with magnet at base and 3" stamped brass tablet.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. PINE</u>	<u>10"</u>	<u>N 88 E</u>	<u>76.5'</u>
<u>ASPEN</u>	<u>5"</u>	<u>N 50 W</u>	<u>43.0'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Birch</u>	<u>15"</u>	<u>N 58 W</u>	<u>133.98'</u>
<u>Birch</u>	<u>10 1/2"</u>	<u>N 66 E</u>	<u>130.83'</u>
<u>Red Oak</u>	<u>11 1/2"</u>	<u>S 55 E</u>	<u>172.61'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1986 Certificate - Ken Whitehorn

Doc # 239675

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____