


Index No. R 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5th Coordinates: X NE R 7 Y Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>FIR</u>	<u>SUGAR</u>	<u>BIRCH</u>	<u>BIRCH</u>
Diameter	<u>10"</u>	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N76W</u>	<u>S39E</u>	<u>S20W</u>	<u>N41E</u>
Distance	<u>10 LKS</u>	<u>21 LKS</u>	<u>30 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN  
Location filed \_\_\_\_\_  
Monument 2" x 54" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Ø' STEEL SIGN POSTS NORTH 2.9, EAST 3.7

	Bearing Trees, Reference Objects			
Species	<u>MAPLE</u>	<u>MAPLE</u>	<u>MAPLE</u>	<u>SPRUCE</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N1W</u>	<u>N63E</u>	<u>S43E</u>	<u>S86W</u>
Distance	<u>29.23</u>	<u>27.75</u>	<u>18.65</u>	<u>30.73</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration R-17

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERT. BY WM. OSUFSEN 1990  
Doc # 323164

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_