


T. 143 R. 26 M. 5TH Coordinates: X NE 25 Corner common to sections 24, 25 AND 19, 30-143-25 Y _____



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>SUGAR</u>	<u>BALSAM</u>	<u>ELM</u>
Diameter	<u>14"</u>	<u>10"</u>	<u>16"</u>
Bearing	<u>N11E</u>	<u>S45E</u>	<u>N59W</u>
Distance	<u>22 LKS</u>	<u>11 LKS</u>	<u>15 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument SET 2 1/2 X 28" ALUM. POST W/ALUM. CAP T143N
R26W R25W
S24 S19
S25 S30

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSUFSEN
END 2 1/2 X 28" ALUM. POST W/ALUM. CAP
STEEL SIGN POST 3.5' SOUTH

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ASPEN</u>	<u>10"</u>	<u>NBE</u>	<u>10 1/2 LKS</u>
<u>ASPEN</u>	<u>14"</u>	<u>S76E</u>	<u>12 1/2 LKS</u>
<u>ASPEN</u>	<u>10"</u>	<u>S20W</u>	<u>29 LKS</u>
<u>ASPEN</u>	<u>14"</u>	<u>N72W</u>	<u>4 1/2 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ASPEN</u>	<u>18"</u>	<u>N70W</u>	<u>27.13</u>
<u>ASPEN</u>	<u>10"</u>	<u>N7E</u>	<u>7.08</u>
<u>ASPEN</u>	<u>12"</u>	<u>S68E</u>	<u>14.00</u>
<u>ASPEN</u>	<u>9"</u>	<u>S20W</u>	<u>18.63</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. WM OSUFSEN 1990
DOC # 319619