


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Birch</u>	<u>Birch</u>	_____	_____
Diameter	<u>6"</u>	<u>10"</u>	_____	_____
Bearing	<u>N28E</u>	<u>S60E</u>	_____	_____
Distance	<u>12LKS</u>	<u>7LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JAMES FLYNN
Location filed COUNTY BOOK "C" P. 160
Monument CORNER GONE - NEW B.T.S. - BELOW

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSUFSEN
SE2 2x54" BR/CAP
SET 8' STEEL SIGN POSTS 4.5 NORTH,
4.2 EAST

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	_____	_____
Diameter	<u>8"</u>	<u>12"</u>	_____	_____
Bearing	<u>N32E</u>	<u>S8E</u>	_____	_____
Distance	<u>15'</u>	<u>31'</u>	_____	_____

Bearing Trees, Reference Objects

<u>MAPLE</u>	<u>MAPLE</u>	<u>BIRCH</u>	_____	_____
<u>7</u>	<u>6</u>	<u>10</u>	_____	_____
<u>N 77 W</u>	<u>N 35 E</u>	<u>S 70 E</u>	_____	_____
<u>17.99</u>	<u>18.03</u>	<u>13.01</u>	_____	_____

Subsequent Corner Restoration V 11

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT BY WM. OSUFSEN 1990
DOC # 335147

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____