


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed \_\_\_\_\_

Year of search \_\_\_\_\_ by \_\_\_\_\_

Original monument \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Monument: \_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Monument: \_\_\_\_\_


Certificate of Location of Government Corner filed in Cass County

By \_\_\_\_\_

Recorders Office as Document \_\_\_\_\_

Date \_\_\_\_\_

T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 31 Corner common to sections 30,31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Distance
<u>Oak</u>	<u>S38E</u>	<u>1045</u>
<u>Aspen</u>	<u>N19E</u>	<u>1245</u>
_____	_____	_____
_____	_____	_____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986 By Ken Whitehorn  
Location filed \_\_\_\_\_  
Monument Set 2 1/2" x 48" galvanized iron pipe with magnet at base and 3" stamped brass tablet.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Oak</u>	<u>N50W</u>	<u>43.78'</u>
<u>W. Oak</u>	<u>S38E</u>	<u>126.13'</u>
<u>Ash</u>	<u>S15W</u>	<u>126.50'</u>
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1986 Certificate - Ken Whitehorn  
Doc # 289680  
May 2002 M. Stefan #12261  
Cert. of Surv shows mon. found