


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____


Certificate of Location of Government Corner filed in Cass County

By _____

Recorders Office as Document _____

Date _____

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Trees	Distance
<u>Aspen</u>	<u>W. Pine</u>	<u>W. Pine</u>	<u>N. Pine</u>
<u>5"</u>	<u>6"</u>	<u>5"</u>	<u>14"</u>
<u>S 55W</u>	<u>N 26W</u>	<u>N 22E</u>	<u>S 22E</u>
<u>6 LKS</u>	<u>20 LKS</u>	<u>15 LKS</u>	<u>75 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "B" P. 81-85

Monument FIND OLD GOVT B.T. STUMPS: 5" W. PINE
N 22E 15 LKS, 6" W. PINE N 26W 20 LKS, 14" N. PINE
S 22E 45 LKS.

also on microf. film - roll 115 BK 71 P. 96

Species	Bearing	Trees, Reference Objects	Distance
<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	<u>W. PINE STUB</u>
<u>3"</u>	<u>4"</u>	<u>4"</u>	<u>5"</u>
<u>S 44-20W</u>	<u>N 56-55E</u>	<u>N 50-21W</u>	<u>S 46-25E</u>
<u>61.80'</u>	<u>39.80'</u>	<u>84.90'</u>	<u>27.00'</u>

Evidence of Subsequent Corner Restoration

Year of search 1918 By JAMES FLYNN

BOOK "C" P. 151 FIND OLD GOVT B.T. STUMP 14" N
PINE S 22E 45 LKS SET IRON - NO TREES FOR B.T.S
IRON IS 2 1/2 x 30" W/ CAP
COUNTY RESURVEY 1918 "E-3"

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1941 By DEFAULT

Location filed ECC NOTES

Monument FIND IRON 24" ABOVE GROUND - CORNER 6 188 CH. N. OF
INTERSECTION OF BOY RIVER - REMER ROAD - ADJACENT TO FENCE
LINE - FENCE N AND E

1982 - CG HWY 1 SURVEYOR - FIND 2" IRON LATING ON GROUND -
DESTROYED BY CONSTRUCTION

1958 - Co. Rd. 11-665-03, corner
assumed to be at road intersection

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1986 Certificate - Ken Whitehorn
DIC. # 259681
SET 2 1/2" x 30" GALVANIZED IRON PIPE WITH
3" STAMPED BRASS CAP DOWN 10"
39" ROCK NORTH 50 74'
POWER POLE S 79 W 105 53'
W OAK 16" S 62 E 141 43'

May 2002 M. Stefan # 12261
Cert of Surv. shows mon. Found