


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X E 1/4 36 Y 36 AND 31 - 143 - 25
Corner common to sections 36 AND 31 - 143 - 25



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument Post

Bearing Trees
 Species TAM. TAM.
 Diameter 10" 10"
 Bearing S46E SSW
 Distance 13 LKS 5 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1976 By BLM
 Location filed SEC. OF STATE
 Monument END U.S.F.S 2 1/2" I.P.W. BRASS CAP T143N
R26W R26N
1/4
S36 / S31

Evidence of Subsequent Corner Restoration
 Year of search 1990 By WM. OSUFSEN
FND 2" X 60" BR. CAP
STEEL SIGN POST 6.3 SOUTH

Bearing Trees, Reference Objects ¹⁹⁶⁸ RLS NO 6807
 Species SPRUCE SPRUCE STEEL SIGN POST
 Diameter 6" 5" 54.2 & 54.4
 Bearing N25E N76E SOUTH
 Distance 29 LKS 22 LKS 9 1/2 LKS
U.S.F.S. TIES

Bearing Trees, Reference Objects
 Species SPRUCE N. PINE ASPEN
 Diameter 7" 22" 6"
 Bearing N 77 E S 10 E S 75 W
 Distance 15.05 96.50 56.35

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE BILL OKERMAN - 1968
C&RT. WM. OSUFSEN 1990
DOC # 319622

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____