


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34 - 144-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

	<u>Dead Jam</u>	<u>Jams</u>	<u>Jam.</u>
Species	<u>Dead Jam</u>	<u>Jams</u>	<u>Jam.</u>
Diameter	<u>10"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N35E</u>	<u>S12W</u>	<u>S1E</u>
Distance	<u>19LKS</u>	<u>150LKS</u>	<u>161LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLD
 Location filed Sec. of State
 Monument Find all 3 BITS - Set 2' long 6" dia Concrete
Mn. w/ brass cap
T144N | R27W
533 | 534
54 | 53

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects ^{T143N 1937}

	<u>Asplar</u>	<u>N. Pine</u>	<u>Birch</u>
Species	<u>Asplar</u>	<u>N. Pine</u>	<u>Birch</u>
Diameter	<u>14"</u>	<u>26"</u>	<u>6"</u>
Bearing	<u>S43 1/4 E</u>	<u>S61W</u>	<u>N80 1/2 W</u>
Distance	<u>106LKS</u>	<u>409LKS</u>	<u>125LKS</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____