


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X NE 5 Y 4,5 AND 32, 33-144-27
Corner common to sections



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees				
Species	<u>Spruce</u>	<u>N. pine</u>	<u>N. pine</u>	<u>Fir</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>S47E</u>	<u>N57E</u>	<u>N12W</u>	<u>S32W</u>
Distance	<u>71LKS</u>	<u>34LKS</u>	<u>53LKS</u>	<u>63LKS</u>

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1937 By GLO
Location filed Sec of State
Monument Proprietary dist - set 2' long 6" dia concrete
men. w/ brass cap
T144W R27W
S32 | S33
55 | 54

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects				
Species	<u>Birch</u>	<u>Br. oak</u>	<u>Elm</u>	<u>Birch</u>
Diameter	<u>6"</u>	<u>11"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N26 1/2 E</u>	<u>S87 1/2 E</u>	<u>S58 3/4 W</u>	<u>N72 1/2 W</u>
Distance	<u>47LKS</u>	<u>81LKS</u>	<u>70LKS</u>	<u>61LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____