Index No. G21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____

E 1/4 11 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Tam	Tam		
Diameter	6"	5"		
Bearing	S87W	East		
Distance	24 Lks	14 Lks		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman

Location filed _____

Monument Set 60" galvanized steel pipe with brass cap.

Bearing Trees, Reference Objects

Species	Tamarack	Tamarack	Spruce	Spruce
Diameter	5"	5"	6"	5"
Bearing	N51E	S16E	N44W	S16W
Distance	38.40'	19.50'	43.90'	34.60'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1975 Certificate - William Okerman
Doc. # 223547

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____