Index No. 6 23 COUNTY	LAND CORNER RECORD
1112 27 1-1	
T. 143 R. 27 M. 5TH Coordinates: X Elly 12 Corner common to sections 12 Awa	7-1/2-26
ETY / Corner common to sections / AM	0 / 1/ 3- 1/
EA16	STING SURVEYS
Original Government Survey	Original Evidence Found
	Year of search By+
Year surveyed 1872	
Original monument 1657	Monument found
Bearing Trees	Original Bearing Trees Found O = Corner
Species Spruce Spruce Diameter 6" 6" Bearing 566W 5476	Species
Diameter 6	Diameter
Bearing _566w _5476	Bearing — — — — — — — — — — — — — — — — — — —
Distance 16LKS 19LKS	Distance — — — — — — — — — — — — — — — — — — —
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of searchBy
Location filed	
Monument	N
monunean	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	
Diameter	ll .
Bearing	\$ N
Distance	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
ear surveyed By	
ocation filed	
donument	
Remonumentation certificate prepared	